ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
13

Ward Name
Mallasandra

Street ID
W0095, W0179, W0202, W0169, W0186, W0167, W0185, W

Street Name
Om Shakthi Lyt 2nd Crs, NA, Vinayaka Lyt 3rd Crs, Om Shakthi Lyt 1st Crs, Chowdeshwari Temple Behind

Significant Landmark
BHEL Mini Colony,Santhosh Nagara,Kalyana nagara Ra

Segment No.
13/C-W0095/S060710

Total Length (m)
1039.63

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	294.93	77.512050	13.049128	77.514689	13.048487	4th Cross	5th Cross
2	56.61	77.511883	13.048597	77.512020	13.049091	2nd Main Kalayana nagar	3rd Main Kalyanagara
3	177.23	77.519308	13.050136	77.518168	13.051283	Rvaindra nagara Main Road	Dead end
4	130.52	77.517800	13.051944	77.517237	13.050902	4th cross Ravindra Nagara	Dead end
5	55.78	77.517486	13.052153	77.517036	13.052396	Ravindra Nagar Main Road	Dead End
6	96.12	77.513058	13.052969	77.513890	13.052668	Ravindra Nagara Main Road	Shooting Bunglow Road
7	155.39	77.515142	13.054866	77.516558	13.054657	11th Cross BHEL Mini Clony	Dead End
8	73.05	77.512929	13.052726	77.513106	13.053358	BHEL Mini Colony Main Road	Shooting Bunglow Road

Work Details

History of Road / Lane / Circles

Name of the Work
Improvments Of Roads And Footpath In Mallasandra Ward No 13 In Shettyhalli Sub Division

Sanctioned Estimated Amount (Rs.)
1500000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Others

Other Work Type

Tender
Not a Tender

Work Details

Job No. / Work Code
013-18-000084

Scanned with CamScanner

Work Order No.	Work Order Date	Period of Extention
EE/DD/45/20-21	20/06/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/08/2020	12/08/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863064		

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0095, W0179, W0202, W0169,

Scanned with CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Venkateshappa
Date of Inspection	**Remarks**	
28/08/2020		

Category	Image	Photo Remark
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0095, W0179, W0202, W0169,

Scanned with CamScanner

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Doddiah	02/12/2020	27/09/2020	Approved
EE	K.S Idrus	31/08/2020	27/09/2020	Copleted
AEE	M Nageshmurthy	29/08/2020	27/09/2020	approved
AE	Vebkateshappa	28/08/2020	27/09/2020	Forward
AE	Venkateshappa	28/08/2020	27/09/2020	Approved

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0095, W0179, W0202, W0169,

Scanned with CamScanner